
DELIVERED BY RAIL/ROAD
QUARTZ
COAL
CHARCOAL
WOODCHIPS
RAW MATERIAL STOCKPILE AREA
RAW MATERIALS FOR 2 FURNACES
164,000 tpa QUARTZ
26,000 tpa CHARCOAL
54,000 tpa COAL
166,000 tpa WOODCHIPS
DAY BINS
DUST EXTRACTION OR SUPPRESSION
WEIGH HOPPERS
FEED BINS
ATMOSPHERE
STACK
BAGHOUSE
GAS COOLING
25,000 tpa SILICA FUME
SMALL BAGS
BULK BAGS
BULK TRANSPORT
FURNACE x2
TAPPING FUME EXTRACTION
TAPPING, REFINING & CASTING
ATMOSPHERE
BAG FILTER PLANT
DUST EXTRACTION
CRUSHING
SCREENING
60,000 tpa SILICON METAL
FINAL PRODUCT
BAGS OR CONTAINERS