WASHINGTON STATE PATROL
BREATH TEST SECTION

REPAIRS AND/OR ADJUSTMENTS ON DATAMASTER

Instrument Location Bellingham Jail #1 Serial 949103

Complaint (s) Reported:

Tip of breath tube missing

Technician Evaluation and Action Taken:

Plastic fitting for breath tube missing. Replaced breath tube.

Technician Judy Lewis ☐ Complete Breath Test

Technician Judy H. Lewis

Field Lab Factory	WORK BEGAN		LOCATION OF WORK	SERVICE TIME
	DATE	TIME		
Field	11/24/2003	17:15	Bellingham Jail	0hrs 20min

209.BTS