WASHINGTON STATE PATROL
BREATH TEST SECTION

REPAIRS AND/OR ADJUSTMENTS ON DATAMASTER

Instrument Location Bellingham Jail Serial # 949103

Complaint (s) Reported:

spare to replace 140104

Technician Evaluation and Action Taken:

140104 taken O/S due to ambient fail error codes. Changed solution, attaching simulator DR4990 with 949103

☑ Complete Breath Test

Technician Jim Van Diest 3-27-07

Technician [signature] Burlington WA

Field Lab Factory	WORK BEGAN		LOCATION OF WORK	SERVICE TIME
	DATE	TIME		
Field	3/27/2007	14:10	Bellingham Jail	0 hrs 20 min