



Publication No. 14-05-019

NUCLEAR WASTE PROGRAM
3100 PORT OF BENTON BLVD
RICHLAND, WA 99354

Working with you for a better Washington.



Publication No. 14-05-019

NUCLEAR WASTE PROGRAM
3100 PORT OF BENTON BLVD
RICHLAND, WA 99354

Working with you for a better Washington.

Ecology Approves Changes to the Permit for the Liquid Effluent Retention Facility's Liner Repair Procedures

The Washington Department of Ecology recently approved a Class 2 modification to Hanford's dangerous waste permit for liner repair procedures at Hanford's Liquid Effluent Retention Facility (LERF).

The U.S. Department of Energy (Permittee) recently found two small liner tears at the top of one of the basins, above the water line. The permit requires the permittee to drain the basin to repair the liner. But the liner vendor reported that the repairs could be done safely without draining the basin.

Ecology approved a change to Section C.5.2.4.1 of Addendum C of the permit to allow the permittee to repair the liner without draining the basin. In addition, Ecology approved wording to allow the vendor to choose the best method to repair the liner.

The permittee also submitted, and Ecology approved, a request for a Temporary Authorization to allow the repair work to proceed more quickly.

You can appeal Ecology's decisions, including approval of this permit change, through the steps in [Revised Code of Washington 43.21B.230](#)

You can find the permit change language, the comment period summary, and the response to comments document at www.ecy.wa.gov/programs/nwp/PI/pages/closedcommentperiods.htm.

If you have questions, please email Hanford@ecy.wa.gov or call 800-321-2008.

Ecology Approves Changes to the Permit for the Liquid Effluent Retention Facility's Liner Repair Procedures

The Washington Department of Ecology recently approved a Class 2 modification to Hanford's dangerous waste permit for liner repair procedures at Hanford's Liquid Effluent Retention Facility (LERF).

The U.S. Department of Energy (Permittee) recently found two small liner tears at the top of one of the basins, above the water line. The permit requires the permittee to drain the basin to repair the liner. But the liner vendor reported that the repairs could be done safely without draining the basin.

Ecology approved a change to Section C.5.2.4.1 of Addendum C of the permit to allow the permittee to repair the liner without draining the basin. In addition, Ecology approved wording to allow the vendor to choose the best method to repair the liner.

The permittee also submitted, and Ecology approved, a request for a Temporary Authorization to allow the repair work to proceed more quickly.

You can appeal Ecology's decisions, including approval of this permit change, through the steps in [Revised Code of Washington 43.21B.230](#)

You can find the permit change language, the comment period summary, and the response to comments document at www.ecy.wa.gov/programs/nwp/PI/pages/closedcommentperiods.htm.

If you have questions, please email Hanford@ecy.wa.gov or call 800-321-2008.