


EXPLANATION

- NO. 2 LEVEL ONLY
Underground mine workings
- Stoped area
- Raise (chevrons point down)
- Foot or head of raise
- Caved workings
- Breccia Zone
- Quartz vein



Data from Western Gold Mining Inc. mine map, 1949