

**WASHINGTON STATE PATROL
BREATH TEST SECTION
REPAIRS AND/OR ADJUSTMENTS ON DATAMASTER**

Instrument Location Bellingham Jail 2 Serial 949103

Complaint (s) Reported:

None

Technician Evaluation and Action Taken:

Perform Quality Assurance Procedure in accordance with protocol of 5/8/02.

Install new Sample Control Board

Install new Power Supply Board

Technician Judy H Lewis Complete Breath Test

Technician *Judy H Lewis*

	WORK BEGAN		LOCATION OF WORK	SERVICE TIME
	DATE	TIME		
FIELD				
LAB	7/31/02	11:00	Bellingham WSP	4+
FACTORY				