

**WASHINGTON STATE PATROL
BREATH TEST SECTION**

REPAIRS AND/OR ADJUSTMENTS ON DATAMASTER

Instrument Location Bellingham Jail #1 Serial 949103

Complaint (s) Reported:

Printer won't accept ticket

Technician Evaluation and Action Taken:

Printer functioned okay upon first check. Removed ribbon and checked for debris. Installed a new printer board, ran breath test. Did not print but ticket ran through. Put old printer board back in, ran test, functioned properly. Voltage is at proper level. Waited and ran test again, ticket accepted and went through okay. Back in service, no repairs.

Technician Judy Lewis Complete Breath Test

Technician *Judy H. Lewis*

Field Lab Factory	WORK BEGAN		LOCATION OF WORK	SERVICE TIME
	DATE	TIME		
Field	11/6/2003	14:30	Bellingham Jail #1	0hrs 45min