

-SITE CHARACTERISTICS

Topography: General Topographic Characteristics flat ridgetop or bench
 Drainage Characteristics: first order stream along 36th Avenue
 Slopes: General 0-20 %; Proposed Drainfield Location 2 %
 Geology: Type of Bedrock & Depth no data terrace deposits (?)
 Vegetation: pasture
 Distance to, and type of, nearest surface water: NA
 (If Less than 250 Feet)
 Distance to nearby wells: NA
 (If Less than 250 Feet)
 Distance to public sewers: NA
 (If Less than 500 Feet)
 Other structures on property: three-bedroom residence 2807 36th

-SOIL SERIES

As mapped by U.S. Soil Conservation Service: _____
 Appears to be (if different from S.C.S. Classification): _____

-SOIL LOGS

<u>Depth</u>	<u>Description</u>	<u>Comments</u>
<u>0'-60'</u>	<u>silt loam</u>	<u>gradually becomes lighter and loses organic content without sharp transitions</u>

<u>Depth</u>	<u>Description</u>	<u>Comments</u>

<u>Depth</u>	<u>Description</u>	<u>Comments</u>

-MAXIMUM SEASONAL GROUNDWATER ELEVATION

Soil Mottling not found Water Table _____
 (Depth Found & Degree of Development) (Depth to Standing Water)

COMMENTS: _____

