



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Franklin House	Provider Number 2189
Address 5713 PARKER RD E,	Approval Status Approved
City, State, Zip Sumner, WA 983902791	Facility Type Residential Care

On 01/02/2018 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative

Victoriana Ireland
Signature

Victoriana Ireland exec. Dir.
Print Name and Title

Deputy State Fire Marshal Don West
2502 112TH ST E
Tacoma WA 98445
(253) 538-3124

Donald West
Signature



Washington State Patrol
 Fire Protection Bureau
 Phone: (360) 596-3900

Business Name Franklin House	Provider Number 2189
Address 5713 PARKER RD E,	Approval Status Disapproved
City, State, Zip Sumner, WA 983902791	Facility Type Residential Care

On 12/14/2017 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

1 Opening protectives.

Opening protectives shall be maintained in an operative condition in accordance with NFPA 80. Where allowed by the fire code official, the application of field-applied labels associated with the maintenance of opening protectives shall follow the requirements of the approved third-party certification organization accredited for listing the opening protective. Fire doors and smoke barrier doors shall not be blocked or obstructed, or otherwise made inoperable. Fusible links shall be replaced promptly whenever fused or damaged. Fire door assemblies shall not be modified.

IFC 703.2

During the facility tour on December 14, 2017 it was observed that the facility failed to maintain the fire doors in the building unobstructed from closing. The findings were:

1. The following resident room doors were found to be wedged open:
 #107, #115, #141, #147.

2 Door Operation

Swinging fire doors shall close from the full-open position and latch automatically. The door closer shall exert enough force to close and latch the door from any partially open position.

(IFC 703.2.3)

During the facility tour on December 14, 2017 it was observed that the facility failed to maintain the fire doors in the building unobstructed from closing. The findings were:

1. The door to the nurses room failed to close and latch.
2. The cross corridor fire separation doors by resident room #113 failed to close and latch.



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name Franklin House	Provider Number 2189
Address 5713 PARKER RD E,	Approval Status Disapproved
City, State, Zip Sumner, WA 983902791	Facility Type Residential Care

On 12/14/2017 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

Next inspection scheduled on or after: 01/13/2018

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Victoriana Ireland
Signature

Victoriana Ireland executive Director
Print Name and Title

Deputy State Fire Marshal Don West
2502 112TH ST E
Tacoma WA 98445
(253) 538-3124

Donald West
Signature