



Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Merrill Gardens at Burien	Provider Number	2406
Address	15020 5 AVE SW,	Approval Status	Approved
City, State, Zip	Burien, WA 98166	Facility Type	Residential Care

On 03/06/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative

Robert Filipovic
Signature

Robert Filipovic Maintenance Director
Print Name and Title

Deputy State Fire Marshal Raul Murcia
PO BOX 42642
Olympia WA 98504
(360) 819-0067

[Signature]
Signature

This document was prepared by Residential Care Services for the Locator website.

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.



Washington State Patrol
 Fire Protection Bureau
 Phone: (360) 596-3900

Business Name	Merrill Gardens at Burien	Provider Number	2406
Address	15020 5 AVE SW,	Approval Status	Disapproved
City, State, Zip	Burien, WA 98166	Facility Type	Residential Care

On 02/26/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

1 Owner's Responsibility

<p>The owner shall maintain an inventory of all required fire-resistance-rated construction, construction installed to resist the passage of smoke and the construction included in Sections 703 through 707 and Sections 602.4.1 and 602.4.2 of the International Building Code. Such construction shall be visually inspected by the owner annually and properly repaired, restored or replaced where damaged, altered, breached or penetrated. Records of inspections and repairs shall be maintained. Where concealed, such elements shall not be required to be visually inspected by the owner unless the concealed space is accessible by the removal or movement of a panel, access door, ceiling tile or similar movable entry to the space.</p> <p>(IFC 701.6 2021)</p>	<p>Findings during inspection were:</p> <p>Facility failed to provide documentation showing annual inspection of fire-resistance-rated construction.</p>
---	--

2 Testing and Maintenance

<p>Sprinkler systems shall be tested and maintained in accordance with Section 901.</p> <p>(IFC 903.5 2021)</p>	<p>Findings during inspection were:</p> <p>Facility failed to provide the following documentation for the automatic sprinkler system;</p> <ul style="list-style-type: none"> - Three-year dry system full flow trip test. - Five-year fire department connection hydrostatic test.
---	--



Washington State Patrol
 Fire Protection Bureau
 Phone: (360) 596-3900

Business Name	Merrill Gardens at Burien	Provider Number	2406
Address	15020 5 AVE SW,	Approval Status	Disapproved
City, State, Zip	Burien, WA 98166	Facility Type	Residential Care

On 02/26/2025 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement

Statement of Violation

Next inspection scheduled on or after: 04/03/2025

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative

Robert Filipovic
 Signature

Robert Filipovic Maintenance Director
 Print Name and Title

Deputy State Fire Marshal Raul Murcia
 PO BOX 42642
 Olympia WA 98504
 (360) 819-0067

[Signature]
 Signature