




Washington State Patrol
Fire Protection Bureau
Phone: (360) 596-3900

Business Name	Franke Tobey Jones Home	Provider Number	000061
Address	5340 BRISTOL ST ,	Approval Status	Approved
City, State, Zip	Tacoma, WA 98407	Facility Type	Residential Care

On 5/30/2019 the Office of the State Fire Marshal conducted an inspection at your facility.

All violations noted during previous related inspection(s) have been corrected.

Owner or Owner's Representative


Signature


Print Name and Title

Deputy State Fire Marshal Lysandra Davis
2502 112 ST
Tacoma WA 984455104
(360) 890-1622


Signature

This document was prepared by Residential Care Services for the Locator website.

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.



Washington State Patrol
Fire Protection Bureau
 Phone: (360) 596-3900

Business Name Franke Tobey Jones Home	Provider Number 000061
Address 5340 BRISTOL ST ,	Approval Status Disapproved
City, State, Zip Tacoma, WA 98407	Facility Type Residential Care

On 4/30/2019 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

1 Admin Fire & Life Safety Inspection

	<p>Unable to inspect the following rooms - no key available:</p> <ol style="list-style-type: none"> 1. Dry pantry - kitchen storage room 2. CEO office 3. COO office 4. REZ store 5. VP office 6. First floor Medical Supply closet
--	---

2 Admin Acceptance - Fire Sprinkler

	<p>The following items were noted in the facility's annual confidence report:</p> <ol style="list-style-type: none"> 1. Fire Sprinkler System is due for 50 year sprinkler head sampling for Grinnell Model Heads: 1) Upright SSU-2 2) Pendant SSP-1 2. Dry pipe valve (from 1953) in first floor library requires replacement - slow leak was detected.
--	--

3 Multiplug adapters.

<p>Multiplug adapters, such as cube adapters, unfused plug strips or any other device not complying with NFPA 70 shall be prohibited.</p> <p>(IFC 605.4 2012 2015)</p>	<p>Findings during the inspection were:</p> <ol style="list-style-type: none"> 1. Multi-plug adapter found in resident room 316 - fixed at time of inspection. 2. Multi-plug adapter found in use on 2nd floor balcony - fixed at time of inspection.
--	---

4 Extension Cords.

<p>Extension cords and flexible cords shall not be a substitute for permanent wiring. Extension cords and flexible cords shall not be affixed to structures, extended through walls, ceilings or floors, or under doors or floor coverings, nor shall such cords be subject to environmental damage or physical impact. Extension cords shall be used only with portable appliances.</p> <p>(IFC 605.5)</p>	<p>Findings during the inspection were:</p> <p>Extension cords in use found in:</p> <ol style="list-style-type: none"> 1. Resident room 316 - removed at time of inspection. 2. First floor storage closet - removed at time of inspection.
---	---

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
 Phone: (360) 596-3900

Business Name Franke Tobey Jones Home	Provider Number 000061
Address 5340 BRISTOL ST ,	Approval Status Disapproved
City, State, Zip Tacoma, WA 98407	Facility Type Residential Care

On 4/30/2019 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

5 Illumination.

Exit signs shall be internally or externally illuminated. Exception: Tactile signs required by Section 1013.4 need not be provided with illumination. (IFC 1013.3 2015)	Findings during the inspection were: Exit signs in main parlor require internal or external illumination. <i>UL924</i>
---	--

6 Securing compressed gas containers, cylinders and tanks.

Compressed gas containers, cylinders and tanks shall be secured to prevent falling caused by contact, vibration or seismic activity. Securing of compressed gas containers, cylinders and tanks shall be by one of the following methods: 1. Securing containers, cylinders and tanks to a fixed object with one or more restraints. 2. Securing containers, cylinders and tanks on a cart or other mobile device designed for the movement of compressed gas containers, cylinders or tanks. 3. Nesting of compressed gas containers, cylinders and tanks at container filling or servicing facilities or in seller's warehouses not accessible to the public. Nesting shall be allowed provided the nested containers, cylinders or tanks, if dislodged, do not obstruct the required means of egress. 4. Securing of compressed gas containers, cylinders and tanks to or within a rack, framework, cabinet or similar assembly designed for such use. Exception: Compressed gas containers, cylinders and tanks in the process of examination, filling, transport or servicing. (IFC 5303.5.3 2012, 2015)	Findings during the inspection were: Unsecured oxygen cylinder found in resident room 316 - fixed at time of inspection.
---	---

This document was prepared by Residential Care Services for the Locator website.



Washington State Patrol
Fire Protection Bureau
 Phone: (360) 596-3900

Business Name	Franke Tobey Jones Home	Provider Number	000061
Address	5340 BRISTOL ST ,	Approval Status	Disapproved
City, State, Zip	Tacoma, WA 98407	Facility Type	Residential Care

On 4/30/2019 the Office of the State Fire Marshal conducted an inspection at your facility.

Code Requirement	Statement of Violation
------------------	------------------------

Next inspection scheduled on or after: 5/30/2019

Right of appeal. Any person may appeal any decision made by the Fire Protection Bureau in accordance with WAC 212-12.

Owner or Authorized Representative


 Signature

TONY DEMARCO DIR. OF BLDG SERVICES
 Print Name and Title

Deputy State Fire Marshal Lysandra Davis
 2502 112 ST
 Tacoma WA 984455104,
 () -


 Signature

This document was prepared by Residential Care Services for the Locator website.