

COWLITZ COUNTY

SITE ID:	Reynolds Metals Aluminum Smelter	Cleanup Site ID: 11796	FS ID: 29
Alternate Name(s):		CHINOOK VENTURES INC LONGVIEW, LONGVIEW ALUMINUM LLC, Millennium Bulk Terminals Longview, Reynolds Metals Aluminum Smelter, REYNOLDS METALS CO, REYNOLDS METALS CO LONGVIEW, REYNOLDS METALS CO LONGVIEW REDUCTION PL, REYNOLDS METALS PCB	
LOCATION:	WRIA: 25	Lat/Long: 46.142 -122.996	View Vicinity Map
Address:	4029 INDUSTRIAL WAY LONGVIEW 98632	Township Range Section 8N 3W 38	Legislative District: 19 Congressional District: 3
STATUS:	Cleanup Started	Rank: 5	View Site Web Page View Site Documents
Responsible Unit: Solid Waste		Site Manager: Schrieve, Garin	Statute: MTCA
Is Brownfield?		Has Environmental Covenant?	Is PSI Site?
NFA Received?		NFA Date:	NFA Reason:

ASSOCIATED CLEANUP UNIT(s)

culID	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID
13780	Columbia River Sediment	Sediment	Ecology-supervised or conducted	Cleanup Started	1.0	
22	LONGVIEW ALUMINUM LLC	Upland	Ecology-supervised or conducted	No Further Action Required		
7024	LONGVIEW ALUMINUM LLC	Upland	Independent Action	Awaiting Cleanup		
12392	Reynolds Metals Aluminum Smelter	Upland	Ecology-supervised or conducted	Cleanup Started		
23	REYNOLDS METALS CO LONGVIEW REDUCTION PL	Upland	Independent Action	Cleanup Complete-Active O&M/Monitoring ongoing		

SITE ACTIVITIES:

Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
CleanupSite		Site Discovery/Release Report Received	Completed	1/2/1989	1/2/1989			Skyllingstad, Paul
CleanupSite		Initial Investigation / Federal Preliminary Assessment	Completed	4/29/1989	4/29/1989		Ecology	Skyllingstad, Paul
CleanupSite		Site Hazard Assessment/Federal Site Inspection	Completed	9/1/1990	12/1/1990		Ecology	Skyllingstad, Paul
CleanupSite		Hazardous Sites Listing/NPL	Completed	2/5/1991	2/5/1991			Skyllingstad, Paul
Milestone		Remedial Investigation and/or Feasibility Study	Completed	2/17/2012	2/12/2015			Barrett, Guy
Milestone		Remedial Investigation and/or Feasibility Study	Completed	3/1/2007	4/1/2009			Skyllingstad, Paul
Milestone		Remedial Investigation and/or Feasibility Study	Completed	6/1/2006	6/1/2009			Skyllingstad, Paul
Milestone		Cleanup Action Plan	In Process	1/18/2016	6/30/2017			Barrett, Guy

Upland		Independent Report Review - Unpaid	Completed	1/2/1989	10/24/1989		Ecology	Skyllingstad, Paul
LUST		LUST - Notification	Completed	11/5/2004	11/5/2004			Johnston, Carol
LUST		LUST - Site Assessment Report	Completed	9/20/2004	9/20/2004			

AFFECTED MEDIA & CONTAMINANTS:

Media:

Contaminant:	Ground Water	Surface Water	Soil	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic	C		R			
Conventional Contaminants, Organic			C			
Metals - Other	C		C			
Petroleum Products-Unspecified			C			
Petroleum-Diesel			RB			
Petroleum-Other	C		C			
Polychlorinated biPhenyls (PCB)		R	R			
Polycyclic Aromatic Hydrocarbons	C		C			

Key:

B - Below Cleanup Level
C - Confirmed Above Cleanup Level
S - Suspected

R - Remediated
RA - Remediated-Above
RB - Remediated-Below

CleanupSiteDetails2014