

PIERCE COUNTY

SITE ID: OCCIDENTAL CHEMICAL CORP Cleanup Site ID: 4326 FS ID: 1212

Alternate Name(s): OCCIDENTAL CHEMICAL CORP, PIONEER AMERICAS INC, PIONEER AMERICAS LLC, PIONEER CHLOR ALKALI CO INC

LOCATION: WRIA: 10 Lat/Long: 47.279 -122.407 [View Vicinity Map](#)

Address: 605 ALEXANDER AVE
TACOMA 98421-4209

Township: 21N Range: 3E Section: 27
Legislative District: 27
Congressional District: 9

STATUS: Cleanup Started Rank: [View Site Web Page](#) [View Site Documents](#)

Responsible Unit: Southwest Site Manager: Wilhelm, Leon Statute: MTCA

Is Brownfield? Has Environmental Covenant? Is PSI Site? Yes

NFA Received? NFA Date: NFA Reason:

ASSOCIATED CLEANUP UNIT(s)

culID	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID
11272	OCCIDENTAL CHEMICAL CORP	Sediment	Ecology-supervised or conducted	Cleanup Started		
11410	OCCIDENTAL CHEMICAL CORP	Upland	Ecology-supervised or conducted	Cleanup Started		

SITE ACTIVITIES:

Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
CleanupSite		Site Discovery/Release Report Received	Completed	3/1/1988	3/1/1988			Wilhelm, Leon
Milestone		Remedial Investigation and/or Feasibility Study	In Process	2/1/2005	6/30/2010			Wilhelm, Leon
Milestone		Remedial Investigation and/or Feasibility Study	Planned	12/1/2005	12/31/2016			Leja, Stan

AFFECTED MEDIA & CONTAMINANTS:

Media:

Contaminant:	Ground Water	Surface Water	Soil	Sediment	Air	Bedrock
Corrosive Wastes	C		C			
Halogenated Organics	C		C			
Metals Priority Pollutants				C		
Non-Halogenated Solvents	C	C		C		
Polychlorinated biPhenyls (PCB)				C		

Key:

B - Below Cleanup Level
C - Confirmed Above Cleanup Level
S - Suspected

R - Remediated
RA - Remediated-Above
RB - Remediated-Below

CleanupSiteDetails2014