

KING COUNTY

SITE ID: **BSB Diversified Co Inc** Cleanup Site ID: 58 FS ID: 2105

Alternate Name(s): BSB DIVERSIFIED, BSB DIVERSIFIED & HEXCEL CORP, BSB DIVERSIFIED CO INC, Heath Plating, HYTEK FINISHES CO 200TH ST, HYTEK FINISHING CO

LOCATION: WRIA: 9 Lat/Long: 47.423 -122.230 [View Vicinity Map](#)

Address: 8202 S 200TH ST Township Range Section Legislative District: 33
KENT 98032 22N 4E 1 Congressional District: 9

STATUS: **Cleanup Started** Rank: 1 [View Site Web Page](#) [View Site Documents](#)

Responsible Unit: Hazardous Waste Site Manager: Fujita, Hideo Statute: MTCA (RCRA)
Is Brownfield? Yes Has Environmental Covenant? Yes Is PSI Site?
NFA Received? NFA Date: NFA Reason:

ASSOCIATED CLEANUP UNIT(s)

culID	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID
983	BSB Diversified Co Inc	Upland	Ecology-supervised or conducted	Cleanup Started		

SITE ACTIVITIES:

Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
CleanupSite		Site Discovery/Release Report Received	Completed	3/1/1988	3/1/1988			Northwest Region
CleanupSite		Site Hazard Assessment/Federal Site Inspection	Completed	4/1/2004	4/1/2004		Local Government	County Health-NW
CleanupSite		Hazardous Sites Listing/NPL	Completed	10/20/2009	10/20/2009			Northwest Region
CleanupSite		Periodic Review	In Process	8/21/2018	11/30/2018			Fujita, Hideo

AFFECTED MEDIA & CONTAMINANTS:

Media:

Contaminant:	Ground Water	Surface Water	Soil	Sediment	Air	Bedrock
Base/Neutral/Acid Organics	S					
Corrosive Wastes	S		S			
Halogenated Organics	C		C			
Metals - Other	C		S			
Metals Priority Pollutants	C		S			
Non-Halogenated Solvents	S					

Key:

B - Below Cleanup Level R - Remediated
C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected RB - Remediated-Below

Phenolic Compounds

S

CleanupSiteDetails2014