

WHATCOM COUNTY

SITE ID:	Blaine Marina Inc	Cleanup Site ID: 63	FS ID: 2888
	Alternate Name(s):		

LOCATION:	WRIA: 1	Lat/Long: 48.992 -122.764	View Vicinity Map
Address: 214 Sigurdson Ave BLAINE 98230	Township: 40N	Range: 1W	Section: 1
			Legislative District: 42 Congressional District: 1

STATUS:	Cleanup Started	Rank: 3	View Site Web Page	View Site Documents
	Responsible Unit: Northwest	Site Manager: Matthews, Cris	Statute: MTCA	
	Is Brownfield?	Has Environmental Covenant?	Is PSI Site? Yes	
	NFA Received?	NFA Date:	NFA Reason:	

ASSOCIATED CLEANUP UNIT(s)

culID	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID
11321	BLAINE MARINA Inc	Sediment	Ecology-supervised or conducted	Awaiting Cleanup		
11455	Blaine Marina Inc	Upland	Ecology-supervised or conducted	Cleanup Started		528216

SITE ACTIVITIES:

Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
CleanupSite		Site Discovery/Release Report Received	Completed	7/12/1990	7/12/1990			Wang, Ching-pi
CleanupSite		Site Hazard Assessment/Federal Site Inspection	Completed	3/1/2001	8/21/2001		Local Government	County Health-NW
CleanupSite		Hazardous Sites Listing/NPL	Completed	8/28/2001	8/28/2001			Northwest Region
CleanupSite		Order/Decree/Amendment	In Process	12/19/2011				Liu, Jing
Milestone		Remedial Investigation and/or FS Work Plan	Completed	7/23/2012	10/4/2012			Liu, Jing
Milestone		Interim Action - Plan	Completed	1/2/2012	7/11/2012			Liu, Jing
Milestone		Interim Action - Construction	Completed	8/20/2012	10/16/2012			Liu, Jing
Upland		Non-LUST Ind Report Received	Completed	2/26/2013	2/26/2013			
Upland		Non-LUST Ind Report Received	Completed	12/10/2012	12/10/2012			
Upland		Non-LUST Ind Report Received	Completed	10/8/2012	10/8/2012			
Upland		Non-LUST Ind Report Received	Completed	12/19/2011	12/19/2011			
Upland		Non-LUST Ind Report Received	Completed	12/10/2012	12/10/2012			

AFFECTED MEDIA & CONTAMINANTS:

Media:

Contaminant:	Ground Water	Surface Water	Soil	Sediment	Air	Bedrock
Non-Halogenated Solvents	S	S	S			
Petroleum Products-Unspecified	C		C			
Petroleum-Diesel				B		
Petroleum-Other				B		

Key:

B - Below Cleanup Level
C - Confirmed Above Cleanup Level
S - Suspected

R - Remediated
RA - Remediated-Above
RB - Remediated-Below

CleanupSiteDetails2014