

**KING COUNTY**

<b>SITE ID:</b>	<b>Dodge of Bellevue</b>	Cleanup Site ID: 6822	FS ID: 89172959
-----------------	--------------------------	-----------------------	-----------------

Alternate Name(s):	Dodge of Bellevue, PERFORMANCE DODGE
--------------------	--------------------------------------

<b>LOCATION:</b>	WRIA: 8	Lat/Long: 47.613 -122.185	<a href="#">View Vicinity Map</a>
Address: 316 116TH AVE NE BELLEVUE 98004	Township: 25N	Range: 5E	Section: 33
	Legislative District: 41	Congressional District: 9	

<b>STATUS:</b>	<b>No Further Action</b>	Rank:	<a href="#">View Site Web Page</a>	<a href="#">View Site Documents</a>
Responsible Unit: Northwest	Site Manager: Maurer, Christopher	Statute: MTCA		
Is Brownfield?	Has Environmental Covenant?	Is PSI Site?		
NFA Received? Yes	NFA Date: 8/8/2018	NFA Reason: NFA-Voluntary Cleanup Program Review		

**ASSOCIATED CLEANUP UNIT(s)**

culID	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID
4893	Performance Dodge	Upland	Voluntary Cleanup Program	No Further Action Required		

**SITE ACTIVITIES:**

Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
CleanupSite		Site Discovery/Release Report Received	Completed	4/1/1989	4/1/1989			Northwest Region
CleanupSite		Reopen Site	Completed	9/19/2016	9/19/2016			Fernandez, Sonia
CleanupSite		Site Status Changed to NFA	Completed	11/15/2004	11/15/2004			
CleanupSite		Site Status Changed to NFA	Completed	8/8/2018	8/8/2018			Maurer, Christopher
LUST		LUST - Notification	Completed	4/1/1989	4/1/1989			
LUST		LUST - Site Characterization Report	Completed	9/19/2016	9/19/2016			
LUST		LUST - Report Received	Completed	9/17/2004	9/17/2004			
LUST		LUST - Report Received	Completed	9/17/2004	9/17/2004			
LUST		LUST - Report Received	Completed	9/17/2004	9/17/2004			
LUST		LUST - Report Received	Completed	9/17/2004	9/17/2004			
LUST		LUST - Report Received	Completed	9/17/2004	9/17/2004			
LUST		LUST - Report Received	Completed	9/17/2004	9/17/2004			
LUST		LUST - Report Received	Completed	9/17/2004	9/17/2004			

LUST		LUST - Report Received	Completed	1/31/1989	1/31/1989			
LUST		LUST - Report Received	Completed	9/17/2004	9/17/2004			
VcpProject	NW1326	VCP Opinion on Cleanup Action	Completed	9/20/2004	11/15/2004			Maurer, Christopher
VcpProject	NW3091	VCP Receipt of Plan or Report	Completed	5/24/2017	5/24/2017			Maurer, Christopher
VcpProject	NW3091	VCP Opinion on Site Cleanup	Completed	9/19/2016	8/8/2018			Maurer, Christopher

**AFFECTED MEDIA & CONTAMINANTS:**

**Media:**

Contaminant:	Ground Water	Surface Water	Soil	Sediment	Air	Bedrock
Non-Halogenated Solvents			RB			
Petroleum-Diesel	RB		RB			
Petroleum-Gasoline	RB		RB			
Polychlorinated biPhenyls (PCB)			RB			

**Key:**

B - Below Cleanup Level  
C - Confirmed Above Cleanup Level  
S - Suspected

R - Remediated  
RA - Remediated-Above  
RB - Remediated-Below

CleanupSiteDetails2014