

WHATCOM COUNTY

SITE ID: **Chevron 90619** Cleanup Site ID: 8836 FS ID: 35363194

Alternate Name(s): CHEVRON 90619, Chevron USA Inc SS 90619

LOCATION: WRIA: 1 Lat/Long: 48.760 -122.488 [View Vicinity Map](#)

Address: 1205 WASHINGTON ST Township Range Section Legislative District: 42

BELLINGHAM 98225 38N 2E 25 Congressional District: 2

STATUS: **Cleanup Started** Rank: 4 [View Site Web Page](#) [View Site Documents](#)

Responsible Unit: Northwest Site Manager: O'Herron, Mary Statute: MTCA

Is Brownfield? Has Environmental Covenant? Is PSI Site? Yes

NFA Received? NFA Date: NFA Reason:

ASSOCIATED CLEANUP UNIT(s)

culID	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID
8528	Chevron 90619	Upland	Ecology-supervised or conducted	Cleanup Started		

SITE ACTIVITIES:

Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
CleanupSite		Early Notice Letter(s)	Completed	8/6/2015	8/6/2015			Myers, Dale R
CleanupSite		Site Hazard Assessment/Federal Site Inspection	Completed	5/8/2017	12/26/2017		Ecology	Tomlinson, Priscilla
CleanupSite		Hazardous Sites Listing/NPL	Completed	2/7/2018	2/7/2018			Musa, Donna
LUST		LUST - Notification	Completed	1/25/1991	1/25/1991			
LUST		LUST - Report Received	Completed	3/11/1991	3/11/1991			
LUST		LUST - Report Received	Completed	1/21/1994	1/21/1994			
LUST		LUST - Report Received	Completed	1/23/1991	1/23/1991			
LUST		LUST - Report Received	Completed	4/22/1994	4/22/1994			
LUST		LUST - Report Received	Completed	8/16/1995	8/16/1995			
LUST		LUST - Report Received	Completed	4/3/1996	4/3/1996			
LUST		LUST - Report Received	Completed	2/27/1992	2/27/1992			
LUST		LUST - Report Received	Completed	8/26/1991	8/26/1991			
LUST		LUST - Report Received	Completed	8/3/1994	8/3/1994			

LUST		LUST - Report Received	Completed	5/21/1991	5/21/1991				
LUST		LUST - Report Received	Completed	11/14/1994	11/14/1994				
LUST		LUST - Report Received	Completed	3/23/1992	3/23/1992				
LUST		LUST - Report Received	Completed	10/26/1995	10/26/1995				
LUST		LUST - Report Received	Completed	9/22/1992	9/22/1992				
LUST		LUST - Report Received	Completed	10/11/1991	10/11/1991				
LUST		LUST - Report Received	Completed	2/10/1993	2/10/1993				
LUST		LUST - Report Received	Completed	1/10/1995	1/10/1995				

AFFECTED MEDIA & CONTAMINANTS:

Media:

Contaminant:	Ground Water	Surface Water	Soil	Sediment	Air	Bedrock
Benzene	C		C			

Key:

B - Below Cleanup Level
C - Confirmed Above Cleanup Level
S - Suspected

R - Remediated
RA - Remediated-Above
RB - Remediated-Below

CleanupSiteDetails2014