

**KING COUNTY**

**SITE ID:** **Cascade Autovon Co** Cleanup Site ID: 8879 FS ID: 36296841

Alternate Name(s): CASCADE AUTOVON, Cascade Autovon Co, CASCADE AUTOVON COMPANY

**LOCATION:** WRIA: 7 Lat/Long: 47.485 -121.792 [View Vicinity Map](#)

**Address:** 12727 412TH AVE SE Township Range Section Legislative District: 5  
NORTH BEND 98045 23N 8E 9 Congressional District: 8

**STATUS:** **Cleanup Started** Rank: 3 [View Site Web Page](#) [View Site Documents](#)

Responsible Unit: Northwest Site Manager: Song, Jing Statute: MTCA  
Is Brownfield? Has Environmental Covenant? Is PSI Site?  
NFA Received? NFA Date: NFA Reason:

**ASSOCIATED CLEANUP UNIT(s)**

cuID	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID
8571	Cascade Autovon Co	Upland	Voluntary Cleanup Program	Cleanup Started		

**SITE ACTIVITIES:**

Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
CleanupSite		Site Discovery/Release Report Received	Completed	6/20/1991	6/20/1991			Northwest Region
CleanupSite		Initial Investigation / Federal Preliminary Assessment	Completed	7/1/2011	7/1/2011		Ecology w/ Contractor	Olsen, Russ
CleanupSite		Site Hazard Assessment/Federal Site Inspection	Completed	5/7/2013	6/28/2013		Ecology w/ Contractor	Musa, Donna
CleanupSite		Hazardous Sites Listing/NPL	Completed	8/8/2013	8/8/2013			Musa, Donna
LUST		LUST - Notification	Completed	6/20/1991	6/20/1991			
LUST		LUST - Report Received	Completed	4/16/1992	4/16/1992			
LUST		LUST - Report Received	Completed	1/25/1993	1/25/1993			
LUST		LUST - Report Received	Completed	11/27/1991	11/27/1991			
LUST		LUST - Report Received	Completed	6/25/1992	6/25/1992			
LUST		LUST - Report Received	Completed	3/14/1994	3/14/1994			
LUST		LUST - Report Received	Completed	5/10/1995	5/10/1995			
LUST		LUST - Report Received	Completed	9/29/1992	9/29/1992			
LUST		LUST - Report Received	Completed	2/6/2018	2/6/2018			

LUST		LUST - Report Received	Completed	10/27/2016	10/27/2016			
VcpProject	NW3098	VCP Opinion on Remedial Investigation	Completed	10/27/2016	8/31/2017			Song, Jing
VcpProject	NW3098	VCP Opinion on Site Cleanup	In Process	2/6/2018				Song, Jing

**AFFECTED MEDIA & CONTAMINANTS:**

**Media:**

Contaminant:	Ground Water	Surface Water	Soil	Sediment	Air	Bedrock
Petroleum-Diesel	B		C			

**Key:**

B - Below Cleanup Level  
C - Confirmed Above Cleanup Level  
S - Suspected

R - Remediated  
RA - Remediated-Above  
RB - Remediated-Below

CleanupSiteDetails2014