

KING COUNTY

SITE ID: **Cascade Autovon Co** Cleanup Site ID: 8879 FS ID: 36296841

Alternate Name(s): CASCADE AUTOVON, Cascade Autovon Co, CASCADE AUTOVON COMPANY

LOCATION: WRIA: 7 Lat/Long: 47.485 -121.792 [View Vicinity Map](#)

Address: 12727 412TH AVE SE Township Range Section Legislative District: 5
NORTH BEND 98045 23N 8E 9 Congressional District: 8

STATUS: **No Further Action** Rank: 3 [View Site Web Page](#) [View Site Documents](#)

Responsible Unit: Northwest Site Manager: Song, Jing Statute: MTCA
Is Brownfield? Has Environmental Covenant? Is PSI Site?
NFA Received? Yes NFA Date: 8/9/2018 NFA Reason: NFA-Voluntary Cleanup Program Review

ASSOCIATED CLEANUP UNIT(s)

culID	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID
8571	Cascade Autovon Co	Upland	Voluntary Cleanup Program	No Further Action Required		

SITE ACTIVITIES:

Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
CleanupSite		Site Discovery/Release Report Received	Completed	6/20/1991	6/20/1991			Northwest Region
CleanupSite		Initial Investigation / Federal Preliminary Assessment	Completed	7/1/2011	7/1/2011		Ecology w/ Contractor	Olsen, Russ
CleanupSite		Site Hazard Assessment/Federal Site Inspection	Completed	5/7/2013	6/28/2013		Ecology w/ Contractor	Musa, Donna
CleanupSite		Hazardous Sites Listing/NPL	Completed	8/8/2013	8/8/2013			Musa, Donna
CleanupSite		Remove site from Hazardous Sites List	Completed	8/9/2018	8/9/2018			Musa, Donna
CleanupSite		Site Status Changed to NFA	Completed	8/9/2018	8/9/2018			Song, Jing
LUST		LUST - Notification	Completed	6/20/1991	6/20/1991			
LUST		LUST - Report Received	Completed	10/27/2016	10/27/2016			
LUST		LUST - Report Received	Completed	9/7/2017	9/7/2017			
LUST		LUST - Report Received	Completed	2/6/2018	2/6/2018			
LUST		LUST - Report Received	Completed	9/29/1992	9/29/1992			
LUST		LUST - Report Received	Completed	5/10/1995	5/10/1995			
LUST		LUST - Report Received	Completed	3/14/1994	3/14/1994			

LUST		LUST - Report Received	Completed	6/25/1992	6/25/1992			
LUST		LUST - Report Received	Completed	11/27/1991	11/27/1991			
LUST		LUST - Report Received	Completed	1/25/1993	1/25/1993			
LUST		LUST - Report Received	Completed	4/16/1992	4/16/1992			
Upland		Petroleum Impacts to Groundwater Model Remedies	Completed	8/9/2018	8/9/2018			
VcpProject	NW3098	VCP Opinion on Remedial Investigation	Completed	10/27/2016	8/31/2017			Song, Jing
VcpProject	NW3098	VCP Opinion on Site Cleanup	Completed	2/6/2018	8/9/2018			Song, Jing

AFFECTED MEDIA & CONTAMINANTS:

Media:

Contaminant:	Ground Water	Surface Water	Soil	Sediment	Air	Bedrock
Petroleum-Diesel	B		RB			

Key:

B - Below Cleanup Level
C - Confirmed Above Cleanup Level
S - Suspected

R - Remediated
RA - Remediated-Above
RB - Remediated-Below

CleanupSiteDetails2014